



Creating Infrastructure with Difference



हिन्दुस्तान स्टीलवर्क्स कन्स्ट्रक्शन लिमिटेड

एनवीसीसी (इंडिया) लिमिटेड की एक सहायक कम्पनी
प्लॉट नॉम्बर 30, विशाखपट्टणम इस्पात संयंत्र, विशाखपट्टणम-530 031.

HINDUSTAN STEELWORKS CONSTRUCTION LIMITED

A Subsidiary of NBCC (India) Limited
P.Box. No. 30, Visakhapatnam Steel Plant, Visakhapatnam-530 031.
दुरभाष-PHONE: 2518294, 2575874,
E-Mail : hsc_lvizag@yahoo.co.in, vizag@hsc_l.co.in
CIN: U27310WB1984GOI026118

Ref. No.: HSCL/VZ/HQ/P/KVS-TPT/2018-125

Date: 04.05.2018

The Principal,
Kendriya Vidyalaya No. 2,
C.R.S. Settipalli,
Tirupati - 517506

Dear Sir,

Sub: Structural stability and Safety of the School Building etc.

This is to certify that the School Building, Staff Quarters, Boundary wall etc. of Kendriya Vidyalaya No.2, C.R.S. Settipalli, Tirupati constructed by H.S.C.L. has been found to be structurally safe and no major defects have been found.

However, it was observed that cracks developed in some of the class rooms, there was seepage from some of the roofs etc. It is advised that some special repairs may kindly be carried out from your end so that the life of the building is further improved.

This is issued as per the request made by your goodself through e-mail dated 20.04.2018.

G. Viswanadham
04/05/18
(G.VISWANADHAM)
HEAD (PROJECTS)